

BMW Z8 Club e.V.



BMW Z8 Club e.V. ♦ Kaiserhammer 45 ♦ D-95168 Marktleuthen

Circular letter to all Club Members!

President
Olaf Hetze
Wittenberger Str. 44
D-80993 München
Germany
☎ +49 (0) 160-8217799
e-mail
Praesident@Z8-Club.de

Your sign, your message from

Our sign
Jürgen Wunderlich

Date
September 11, 2006

Treasurer
Jutta Haenisch
Priscoß-Str. 18
D-63755 Alzenau
Germany
☎ +49 (0) 171-4218218
e-mail
Finanzen@Z8-Club.de

Availability Retrofit Performance Package for BMW Z8

Dear club members,

with great expectations, we eagerly waited for the performance package, which has now, after significant efforts become available at the BMW dealerships in Germany.

**The BMW Part No. is 51 71 0 420 758
and the price without installation is EUR 371.20 incl. VAT.**


Chairman for Technic
Jürgen Wunderlich
Kaiserhammer 45
D-95168 Marktleuthen
Germany
☎ +49 (0) 9235-967400
e-mail
Technik@Z8-Club.de

**Chairman for Sports
and Tourism**
Norbert Galasso
Püntenstr. 13
CH-8143 Stallikon
Switzerland
☎ +41 (0) 44-7778370
e-mail
Touristik@Z8-Club.de

The retrofit can be performed by any BMW dealer or representation, and according to the installation manual is calculated with approx. 8.5 hours work time. Prior to the installation, the car's software will be updated to the latest version, and an alignment will be performed. The Performance Package consists of two strut tower supports (incl. attaching parts) and a strut brace, which will be attached to the frame structure in front of the strut tower.

**Chairman for Public
Relations**
Helge Brauch
Varoneser Str. 1
D-81547 München
Germany
☎ +49 (0) 89-64270430
e-mail
Oeffentlichkeit@Z8-Club.de

Mailing Address
BMW Z8 Club e.V.
Club Office
Jürgen Wunderlich
Kaiserhammer 45
D-95168 Marktleuthen
Germany
☎ +49 (0) 9235-967450
☎ +49 (0) 9235-967460
e-mail
Sekretariat@Z8-club.de



Internet
www.Z8-Club.de

Bank Account
Sparkasse
Aschaffenburg-Alzenau
Account-Nr.: 8463929
Bank Code: 795 500 00
IBAN:
DE 60 7955 0000 0008
4639 29
SWIFT-BIC:
BYLADEM 1ASA

Headquarter
München, VR 19058

The Performance Package can not be used on ALPINA V8 Roadsters, because the strut brace would make contact with the engine. Whether or not there will be a special retrofit for Alpina cars is unknown to me at this point.

For installation, the front wheels, the inner covers of the wheel houses, the headlamps, and the air intake housings will be dismantled. The strut brace will be

attached on both sides in 3 places using blind rivet nuts (12 mm bores needed in frame structures) and torx screws (M8). The strut supports will be supported by an additional reinforcement ring from above.


Illustration strut support



Attaching points strut brace



Installation position in the car (strut brace is not attached, but only positioned in the picture!)



Many thanks and best regards.

Representing the Board



Jürgen Wunderlich
Acting President

Attachment: Installation manual retrofit Performance Package BMW Z8
(currently available in German only)